



# Case Study: Interconnectivities between Shoreline Type and Structural Vulnerability

The Role of Mangroves in Mitigating Damage due to Hurricane Irma in the Florida Keys

Tori Tomiczek, Kelsi Furman, Brittany Webbmartin, Kiera O'Donnell, Steven Scyphers



ICCE 2018 Short Course: Natural and Nature-Based Features (NNBF) For Coastal Resilience


Sunday, 29 July 2018 Baltimore, MD USA



# Outline

1. Introduction: The Florida Keys and Hurricane Irma

- 2. Post-Storm Reconnaissance
  - a. Shoreline Damage- Island and Parcel Scales
  - b. Structural Damage- Parcel Scale
- 4. Interconnectivities between Hazard, Shoreline Archetype, and Physical Damage
- 5. Homeowner Perceptions of Shoreline Performance
- 6. Ongoing Work and Next Steps





# ICCE 2018 UNITED STATES NAVAL ACADEMY

# Florida Keys: Structural Consistency, Shoreline Variability









#### Hurricane Irma

Duration	30 August-16 September, 2017		
Keys Landfall	Cudjoe Key, 10 September, 2017, 1310 UTC, Category 4		
Central Pressure	914 mBar (min)*; 929 mBar (Keys landfall)		
Wind Speeds	185 mph (maximum)**; 130 mph (Keys landfall)		
Storm Surge	3 m (Florida Keys)		
Effects	Catastrophic damage in Barbuda, USVI, Caribbean, middle Florida Keys, >146 deaths		
US Property Damage	\$53.4 billion***		

\* 2<sup>nd</sup> most intense of 2017 (behind Hurricane Maria)


- \*\* Strongest of 2017
- \*\*\* 5<sup>th</sup> costliest in US History





# Hurricane Irma: Hazard Intensity Measures

ADCIRC + SWAN storm simulation courtesy CERA (2017)




	Key West	Big Pine Key
Wind Velocity (m/s)	44.8-49.2	49.3-53.6
Inundation Depth (m)	1.23-2.14	1.53-2.75
Significant Wave Height (m)	0-1.83	0.92-2.74








# Island Scale Vulnerability







#### Parcel Scale Damage Assessments












- **NEU-USNA** Collaborative Effort
  - July 2017- present ۲
- Key West and Big Pine Key
- Investigate relationship between shoreline resiliency, structural vulnerability, and shoreline management
- October Survey: 263 residential structures, 332 shorelines

### **Shoreline Archetypes**



USI

# Shoreline Damage







Mangrove: broken

branches, loss of

foliage, regrowth

Revetment: rocks displaced



Sandy Beaches: erosion



Bulkhead: cracks, undercutting, structural collapse 10








# **Shoreline Damage Descriptions**

Shoreline Type	0	1	2	3
Mangrove	No Visible Damage	Aesthetic damage; loss of foliage; loss of <25% of mangrove tract in the form of dead/uprooted trees	Loss of 25-50% of mangrove tracts in the form of dead/uprooted trees	Loss of >50% of mangrove tract in form of uprooted/dead trees
Sandy Beach	No Visible Damage	Aesthetic damage; loss of <25% of vegetation/dune grasses; minor evidence of erosion	Loss of 25-50% of vegetation; significant erosion (>12" average dune height or shoreline recession per property)	Loss of >50% of vegetation; major erosion (>3' average dune height or shoreline recession per property)
Bulkhead/ Vertical Wall	No Visible Damage	Nonstructural/ aesthetic damage to components; repairs include patching concrete; repointing mortar, applying a skim coat	Failure or partial failure of structural elements including crumbling, bulging, collapsing, horizontal cracks>2" and scour>6"	Complete failure/ collapse of structure
Revetment	No Visible Damage	Nonstructural/aesthetic damage to components; repairs include resetting fallen stones; <10% armament rocks displaced	Failure or partial failure of structural elements including crumbling, bulging, collapsing, horizontal cracks>2" and scour>6"; 10-25% armament rocks displaced	Complete failure/ collapse of structure >25% armament rocks displaced, requiring complete repair
Hybrid	No Visible Damage	Aesthetic damage; loss of <25% of vegetation; minor evidence of erosion <10% displaced rocks from sills	Loss of 25-50% of vegetation; significant erosion: >12" shoreline recession; 10-25% displaced armament rocks; partial failure of structural elements	Loss of >50% of vegetation; major erosion: >3' shoreline recession >25% displaced rocks; complete failure




#### Standardized Shoreline Damage Assessments






# Standardized Shoreline Damage Assessments





# Standardized Shoreline Damage Assessments

- 56 surveyors, 12 shorelines
- 95 % Confidence
   Intervals > 0.5 DS
- Larger variation for intermediate damage states








#### Component-Based Structural Damage Assessments

Component	0	1	2	3	4
Roof	• No visible	<ul> <li>Few shingles missing (&lt;15% of roof area)</li> <li>Minor damage to gutters</li> </ul>	• Significant amount of shingles missing 15-30% of roof area)	<ul> <li>Holes in roof due to debris or wind- sheathing is exposed but not</li> </ul>	• Large parts of roof are missing or collapsed; structural damage
	damage	- Willor damage to gutters	<ul> <li>Minor damage to frame</li> </ul>	house interior	or conapsed, structural damage
	Ū		Roof interior is not exposed		
Walls	• No	<ul> <li>Minor cladding removal (&lt;10% of 1 wall)</li> </ul>	<ul> <li>Cladding removed from &gt;25% of wall surfaces</li> </ul>	<ul> <li>Minor structural wall damage,</li> </ul>	•Walls have collapsed, bent or ar
	visible	<ul> <li>Small scratches/ aesthetic damage</li> </ul>	•Interior sheathing exposed on <25% of house	including debris caused holes or	out of plumb, structural damage
	damage		but insulation and house interiors are not	repairable damage	<ul><li>Large holes in walls</li><li>major structural damage</li></ul>
Foundation	• No	<ul> <li>Scour &lt;0.5 feet around foundation</li> </ul>	• Scour 0.5-2' deep	<ul> <li>One pile out of plumb, or</li> </ul>	Major foundation damage
	visible	<ul> <li>Water marks around foundation</li> </ul>	<ul> <li>Structurally sound foundation</li> </ul>	damaged	<ul> <li>Differentially settlement</li> </ul>
	damage	<ul> <li>Structurally sound</li> </ul>	<ul> <li>Evidence of weathering/minor damage on</li> </ul>	<ul> <li>Scour &gt;2' deep</li> </ul>	<ul> <li>&gt;1 pile is damaged</li> </ul>
			piles	<ul> <li>Minor damage to foundation</li> </ul>	<ul> <li>House is missing</li> </ul>
Landscaping,	• No	<ul> <li>&lt;2 Exterior structures damaged or</li> </ul>	<ul> <li>2 or more exterior structures are gone or</li> </ul>	<ul> <li>Collapse of detached garage</li> </ul>	
Attachments and	visible	removed	destroyed	<ul> <li>Shoreline- complete damage</li> </ul>	
Detached Structures	damage	<ul> <li>Damage to stair, porches, detached</li> </ul>	Damage/ collapse of deck, shed		
(If Waterfront,		garage, or walkways, most structures	<ul> <li>Landscaping damage- &gt;50% of trees, bushes</li> </ul>		
Shoreline Condition)		remain in tact	uprooted		
		<ul> <li>Shoreline- aesthetic damage</li> </ul>	<ul> <li>Shoreline- moderate damage</li> </ul>		
Openings: Windows,	• No	<ul> <li>1 window or door is broken (glass only)</li> </ul>	<ul> <li>2+ windows/doors broken or removed</li> </ul>		
Doors, Attached	visible	<ul> <li>Screens may be damaged or missing</li> </ul>	<ul> <li>Damage to frames of doors and windows</li> </ul>		
Garages	damage		<ul> <li>Attached garage door damaged or gone</li> </ul>		
	• No	•No flooding	Slight evidence of flooding	<ul> <li>Water marks (1'-4')</li> </ul>	Water marks 4' or higher
	visible	<ul> <li>Minimal/no evidence of rain intrusion-</li> </ul>	<ul> <li>Water marks (0-1') above floor</li> </ul>	<ul> <li>Rain/water damage to ceiling: wet</li> </ul>	<ul> <li>Structural ceiling damage from</li> </ul>
Interior	damage	minor water damage in corners or around	• Evidence of rain intrusion- dampness/ minor	spots, dripping, or sagging	rain- wet spots and sagging
		windows only	water damage on <10% of wall area or ceiling	• Dampness on >25% of wall areas	<ul> <li>Structural damage to interior</li> </ul>
		Minor water damage to interior	Water damage to interior furnishings	and evidence of dripping or cracks	walls
		furnishings	• No mold	on walls	
				•Mold	



#### Structural Fragility: Relate Hazard to Structural Damage (?) 5 4.5 0 4 0 00 നറ 0 lhsm 3.5 wave crest fb] elevation 3 0 0 0 2.5 DS 2 0 0 О 1.5 1 | 0 ocomp 0 0 0.5

0000000

3

4

2

00

-1

0


-fb (m)


0

-0.5 L -2

fb=freeboard DS= damage state

# Relate Hazard, Structural Damage, and Shoreline Type








Multinomial Logistic Regression:

- Shoreline Damage, Structural
   Damage as ordinal response variables
- Shoreline type (mangrove vs. other) as a categorical predictor variable

$$Y_{i,k} \sim \prod_{i=0}^{1} \frac{N!}{Y_{i,k}!} P(DS = DS_i | x_k)$$

Statistical Significance and AIC for Empirical Multinomial Fragility Models

Model	$p_{fb}$	$p_{\eta wave}$	$p_{Shoreline}$	AIC
Shoreline		0.0028	$1.32 \ge 10^{-23}$	161
Structure	0.041		$4.89 \ge 10^{-24}$	271
	-			





# Interconnectivities between Shoreline Type, Structural Damage, and Homeowner Perceptions


100%

- Mixed mode interviews
- Perceived impact of mangroves, seawalls, and beaches, on social and ecological systems during Hurricane Irma

"Mangroves are the only thing keeping the island from eroding"

"90% of beaches were swept away"

"Without mangroves, the impact of the storm would have been much worse"



Seawalls

Beaches

Mangroves

Positive
 No Impact
 Negative

# **Ongoing Work**

- July, 2018: Field study to characterize mangrove prop root density, ۰ average diameter, elastic modulus, canopy characteristics
- Fall, 2018: 1:16 scale laboratory experiments ۰
  - Effects of roots, leaves, scaling

Spring, 2019: Field experiments, Key West, FL ۲







# Conclusions

- Case study of damage to shorelines, structures after Hurricane Irma
- Ongoing longitudinal investigation to identify recovery trends, repair decisions
- Natural and nature-based features may mitigate overland flow and resulting inland damage during storm events in coordination with engineered structures
  - Need quantitative measurements!







